

BUILDING SAFETY CERTIFICATE

No. X11/146/25Dated: 15/7/25

It is certified that the existing building Uttam Public School (name of the building or premises) at Rahawati, Mawana, Meerut (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor(s) in the Block	G + 1	NA	NA	NA	NA	NA

The building is owned/occupied by Uttam Public School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Rular Engineering Services , Rahawati, Mawana, Meerut (Name of Department/Govt.) on 11/7/25 (date of inspection) in the presence of Mr. Ram Kumar, Vill – Rahawati, Mawana, Meerut (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 15/7/25 for a period of 03 years in accordance with rule and subject to compliance of the specific

conditions as appended.

1. }
 2. }
 3. }
 4. }
- NA

Issued on 15/7/25 at _____ by _____

(Signature)
अमित कुमार
ग्रामीण अभियन्ता
प्रखण्ड - मेरठ

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : _____

Name & Address of Department/Office: _____